## **Inlet Protection**

## The Good.....



Straw wattle over inlet to keep sediment from laden storm water from entering the storm sewer.



Protection around area inlet.



Inlet basket insert

## The Bad.....



Inappropriate use of a rock sock over an Inlet.



The Illinois Urban Manual does not allow fabric for inlet protection.



There should be no gaps on the upslope side That would allow sediment to enter the inlet.

## The Ugly.....



Inlet basket that is not being maintained.



No inlet protection



Rock sock inlet protection that is not being maintained.